


-Opening for wire Routing Access Through Robot Wrist

ITEM NO.	QTY	PART NUMBER	DESCRIPTION
1	1	9120-027HM-000-000-S0-E-6160	QC-27 Hollow Wrist Mount Master, No Sensors, Black, With 4mm Push Tube Fittings, and 6160 IP
2	1	9120-027T-000-000-E	QC-27 Tool, Black, with 8 1/8" G Pass Through Ports

NOTES:

- Mounting Hardware Included on Master Side.
 Drawing shows a master side assembly with interface plate for direct mount to Fanuc M10ia and M20ia Hollow Wrist Robots.
 Other versions available upon request.
 Tool side fittings not supplied.



	INDUSTRIAL AUTOMATION

DRAWN BY: L.Hines 8/9/16	QC-27 Base Tool Changer, BSPP, With IP 6160
HECKED BY: TB 8/19/16	

PROJECT # SHEET 1 OF 3 1:1.5 3rd ANGLE PROJECTION

DRAWING NUMBER В


9630-20-027H-E


REVISION

03

QC-27 Master Assembly 0 0 20 14 0 0 NOTES: UNLESS OTHERWISE SPECIFIED. 1031 Goodworth Drive, Apex, NC 27539, USA Tel: +1.919.772.0115 www.ati-ia.com Fax: +1.919.772.8259 ISO 9001 Registered Company INDUSTRIAL AUTOMATION DO NOT SCALE DRAWING. ALL DIMENSIONS ARE IN MILLIMETERS. PROPERTY OF ATI INDUSTRIAL AUTOMATION, INC. NOT TO BE REPRODUCED IN ANY MANNER EXCEPT ON ORDER OR WITH PRIOR WRITTEN AUTHORIZATION OF ATI. DRAWN BY: L.Hines 8/9/16 QC-27 Base Tool Changer, BSPP, With IP 6160 CHECKED BY: TB 8/19/16 DRAWING NUMBER REVISION 1:1.5 B 03 PROJECT # SHEET 2 OF 3 9630-20-027H-E 3rd ANGLE PROJECTION

QC-27 Tool Assembly






NOTES: UNLESS OTHERWISE SPECIFIED.

DO NOT SCALE DRAWING. ALL DIMENSIONS ARE IN MILLIMETERS.





DRAWN BY: L.Hines 8/9/16 QC-27 Base Tool Changer, BSPP, With IP 6160 CHECKED BY: TB 8/19/16

1:1.5 B PROJECT # SHEET 3 OF 3

DRAWING NUMBER REVISION 9630-20-027H-E 03